

The following photographs show the areas of the river where the 1995 and the modeled cutoff are located. **Photograph 1** is looking downstream with the Road 29 levee and bank protection located on the right side of the photograph. This area is where the modeled breach would begin. **Photograph 2** is looking south from Road 29 and shows the modeled cutoff path across Kimmelshue Bend. **Photograph 3** is a view looking north across the Sacramento River at the location where the modeled cutoff would re-enter the river.



Photograph 1. Looking Downstream along the Sacramento River with the Road 29 Embankment along the Right Side (RM 188.0)